

## SAFETY CERTIFICATE OF KV SCHOOL BUILDING AT INS KALINGA


1. As per the request of the Principal, KV INS Kalinga, Bheemunipatnam and with reference to letter No 1502116/KV KLG/2020-21 dated 24 May 2021. I personally visited 'KV INS Kalinga and inspected the Vidyalaya building. Based on my observation, I (Arnab Dey, EE, GE (P) Navy Kalinga and Arunavo Roy, AE (Civ) AGE BR (Maint) Kalinga) certify that the Vidyalaya building is safe for conducting classes. The Vidyalaya building which was constructed by MES on 1999 structurally strong and stable. Minor cracks/ defects are seen on walls, but there is no such problem for conducting classes as on date. However, it is recommended that some cracks/ defects may be rectified at the earliest to make the building safer.
2. It is also suggested that immediate periodical maintenance work may be carried out under the supervision of qualified Civil Engineer.
3. It is certified that the building of Kendriya Vidyalaya, is safe for conducting classed on date.

Station : Bheemunipatnam

Dated : 25 May 2021

  
(Arunavo Roy)  
AE (Civ)  
AGE BR (Maint) Kalinga

  
(Arnab Dey, IDSE)  
EE  
Garrison Engineer

  
प्राचार्य / PRINCIPAL  
केन्द्रीय विद्यालय / KENDRIYA VIDYALAYA  
भा. नौ. पो. कलिंग / I.N.S. KALINGA  
भीमनिपट्टणम-531 163 (ए.पी.)  
BHEEMUNIPATNAM-531 163 (A.P.)